

System 5

DRAWINGS

- 1: PANEL & CLIP PROFILE
- 2: PANEL SEALANT
- 3: LOCKING EAVE FLASHING
- 4: LOCKING EAVE FLASHING
- 5: HI— EAVE FLASHING
- 6: RAKE GABLE FLASHING
- 7: RIDGE HIP COVER
- 8: FLOATING VALLEY
- 9: ROOF TO WALL FLASHING
- 10: PITCHBREAK FLASHING









SUBJECT: PANEL SEALANT


System 5

DATE: 8-28-00

REV: 2-1-06

DRAWING NO.

2






System 5

NO. DATE: 8-28-00


REV: 2-1-06






SUBJECT: LOCKING EAVE FLASHING NO. DATE: 8-28-00 4 System 5

REV: 2-1-06





SUBJECT: HI-EAVE FLASHING **DRAWING** NO. DATE: 8-28-00 System 5 REV: 2-1-06





SUBJECT: RAKE-GABLE FLASHING


System 5

DATE: 8-28-00

REV: 2-1-06

6

DRAWING NO.





SUBJECT: RIDGE—HIP FLASHING


System 5

DATE: 8-28-00

REV: 2-1-06

DRAWING NO.

/



RYERSON


SUBJECT: FLOATING VALLEY

System 5

DATE: 8-28-00

REV: 2-1-06

DRAWING NO.





SUBJECT: ROOF TO WALL FLASHING


System 5

DATE: 8-28-00

REV: 2-1-06

DRAWING NO.

9





SUBJECT: PITCHBREAK FLASHING

System 5

DATE: 8-28-00

REV: 2-1-06

DRAWING NO.

10